




| Ref: | Legend |
|------|--|
| | <p>window repair codes</p> <ol style="list-style-type: none"> 1. Good - sound and operational - prepare surfaces and redecorate. 2. Intact - ease and free-up moving parts, address surface defects (or corrosion), adjust, redecorate. 3. Moderate - Requires repair, adjustment, refurbishment prior to redecoration. 4. Poor - significant repairs, alterations or new components needed to make operational. Adjust, redecorate. 5. Beyond economic repair - remove. Prepare opening for replacement unit. |



general

- all drawings are copyright
- do not scale drawing
- report all discrepancies to project administrator
- all dimensions to be checked on site

key

notes

Stage 4 - Tender

* NOTE: If window beads do not allow for the installation of standard float glass then 'Horticultural Glass' to be used.

rev

T1: 31.01.19 - Draught Stripping Option Added + NBS Notation Updated

| | | | |
|--|--------------|-----------------------|--------|
| project title: | date: | scale: | drawn: |
| Tavistock Guildhall and Police Station | October 2018 | 1:25@ A1 1:50 @ A3 | cm |
| drawing title: | job no: | drawing no: | rev: |
| External Window Repair Schedule 3 - West Elevation | 1041 | C-357 | T1 |

gillespie yunnie architects

Lower Tweed Mill Shimmers Bridge Dartington Devon TQ9 6JB t 01803 860010 f 01803 864929 e info@gyarchitects.co.uk