

Ref: GD08

Location:Magistrates Building, Ground floor. Type Existing: Timber door. Proposed Works:

Replace with timber door with glazed infill panels.

Repair Code

Glazing: Impact resistant Laminated Glass Subframe/ surround:

To all granite mullions and window surrounds, strip back all paintwork,

Ironmongery:

New ironmongery - simple level handle (as per internal schedule) and SBD compliant locking and

Finish:

Paint doors with 2no. undercoats and finish with

1no. gloss finishing coat. Colour: White - TBC external M60/123 internal M60/150

Spec Reference: L20/270

Ref: GD09

Code: 3

Location:
Police Station, Ground Floor

Type Existing:
Half glazed timber frame door.
Proposed Works:

Burn off all peeling paint and prime timber. Cut out and replace defective sections of frame. Rehang door to open outwards. Replace weather bar. Cut out defective putties. Remove old and defective mastic surrounding door and replace. Prepare and paint door and surrounding. Repair Code:

< GD13

Ironmongery: to be refurbished and/ or replaced where required. Finish: Paint doors with 2no. undercoats and finish with 1no. gloss finishing coat. Colour: White - TBC

external M60/123 internal M60/150 Spec Reference: L20/272 Comments:

Subframe/ surround:

Rot apparent throughout / There is significant paint peel to the plaster window reveals.

Strip back all paintwork where peeling and repaint with breathable paint.

Ref: GD10

Location Police Station, Ground Floor Type Existing: Timber frame boarded door Proposed Works: Replace with timber door with glazed infill panels. Repair Code


Glazing: Impact resistant Laminated Glass Subframe/ surround:

Strip back all paintwork where peeling and repaint with breathable paint.

Ironmongery: New ironmongery - simple level handle (as per internal schedule) and SBD compliant locking and

Finish: Paint doors with 2no. undercoats and finish with 1no. gloss finishing coat. Colour: White - TBC external M60/123 internal M60/150

Spec Reference: L20/270



Ref: GD11

Location:
Police Station, Out-buildings, Ground Floor Type Existing: Timber door. Proposed Works:

Burn off all peeling paint and prime timber. Cut out and replace defective sections of frame. Prepare and paint door and surrounding. Repair Code Code: 3



Glazing: Not required

Subframe/ surround:

Strip back all paintwork where peeling and repaint with breathable paint. Ironmongery:
to be refurbished and/ or replaced where required.

Finish: Paint doors with 2no. undercoats and finish with 1no. gloss finishing coat. Colour: White - TBC

external M60/123 internal M60/150 Spec Reference:

L20/272



GD12 + GD14: **No Survey Drawings or Photos Available**

Ref: GD12 + GD13 + GD14

Police Station, Out-buildings, Ground Floor Type Existing: Timber door.

Proposed Works: Burn off all peeling paint and prime timber. Cut out and replace defective sections of frame. Prepare and paint door and surrounding.

NOTE: GD14 - New Door Required Repair Code:

Glazing: Not required

Subframe/ surround: Strip back all paintwork where peeling and repaint

with breathable paint. Ironmongery: to be refurbished and/ or replaced where required.

Finish: Paint doors with 2no. undercoats and finish with 1no. gloss finishing coat. Colour: White - TBC

external M60/123 internal M60/150 Spec Reference L20/272

Comments:

Ref: GD45 Location:

Police Station, E3 Courtyard Type Existing: Timber gate door.

Proposed Works: Burn off all peeling paint and prime timber Cut out and replace defective sections of

Repair Code: Code: 3

frame.

Ironmongery: to be replaced to match existing Finish:

Paint doors with 2no. undercoats and finish with 1no. gloss finishing coat. Colour: White - TBC external M60/123 Spec Reference: L20/272



Ref: GD07

Location: Courtroom, E1 Courtyard Type Existing: Timber gate door. Proposed Works: Remove and replace with frameless glazed door I 10 555. Ironmongery: New ironmongery Finish: Refer to Extension Drawings

Ref: Legend window repair codes Good - sound and operational - prepare surfaces and redecorate. 2. Intact - ease and free-up moving parts, address surface defects (or corrosion), adjust, redecorate. Moderate - Requires repair, adjustment, refurbishment prior to redecoration. Poor - significant repairs, alterations or new components needed to make operational. Adjust, redecorate. Beyond ecomonic repair - remove. Prepare opening for replacement unit.

Window Key -**Guildhall Square East Elevation** as existing - 1:200 @ A1 ~~~ GD12 + GD13 +

all drawings are copyright do not scale drawing report all discrepancies to project administrator all dimensions to be checked on site

Stage 4 - TENDER ISSUE

T1: 31.01.19 - NBS Notation Updated / New Door Proposals Added

T2: 10.04.19 - Notation Updated



gillespie yunnie architects

ower Tweed Mill Shinners Bridge Dartington Devon TQ9 6JB t 01803 860010 f 01803 864929 e info@gyarchite