
window types and treatments


 $\mbox{L10/210}$ Timber sash windows - Undertake timber repairs, overhaul and redecoration

 $\mbox{L10/220}$ Fixed timber windows - Undertake timber repairs, overhaul and redecoration

L10/310 Crittall steel window in timber subframe. Undertake repairs, overhaul and redecoration

L10/210 Timber sash windows - Requiring significant structural repairs, overhaul and redecoration.







tavistock guildhall TTC: south elevation - as proposed

Note: Pitch of Lift Extension Roof - TBC with Conservation Officer

general	key	notes Stage 4 - Tender	rev T1: 08.02.19 - NBS Specification References Amended	Tavistock Guildhall and Police Station	date: Oct 2018	^{cale:} :50 @ A1 :100 @ A3	drawn: if
 all drawings are copyright do not scale drawing report all discrepancies to project administrator all dimensions to be checked on site 		Stage + - Tender		Window Repair - South+River Elev.	job no: di 1041 C	awing no: GA-234	rev: T1
		Note: Alterations and upgrades to existing fabric detailed on demolition plans, details and specification		gillespie yunnie architects			

Refer to 1041-GA-122 for extended elevation

tavistock guildhall river / market east elevation as proposed