## TAVISTOCK GUILDHALL GATEWAY PROJECT

# QUESTIONS & RESPONSES DURING TENDER PERIOD

Question number	Date added	Question	Response	Responder	Date of Response	Date of posting
Issue 1						
1	21/05/2019	Queries regarding quantities clarified as follows:-				
		Room LG14		THA	21-May-19	
		BQ 4a / Page 11: insert quantities	Item A is 4 m2 of floor covering			
			Item B is 5 m of skirting			
		Room F42				
		BQ 6a / Page 10: amend quantity	Item C is 2 m2 of ceiling boarding			
		BQ 6c / Page 19; insert quantity	Item A is 3 m2 of ceiling			
			Item B is 4 m of edge treatment			
		BQ 6c / Page 19; amend quantity	Item C is 3 m2 of carpet			
		BQ 6c / Page 19; omit	Item G deleted (insert 0 for quantity)			
		Room F45				
		BQ 6a / Page 15; insert quantity	Item A is 74 m2 of floor covering			
		Rooms \$56-58				
		BQ 7a / Page 12; insert quantity BQ 7c / Page 18; insert quantity	Item L is 2 m2 of bulkhead			
		BQ 7C / Page 18; insert quantity	Item C is 43 m2 of ceiling painting			
2	28/05/2019	Query regarding floor lining in new opening between				
	20, 00, 2013	<u>F46/48</u>				
		Measured as metal sheet but shown on drawing GA-		THA	28-May-19	
		152 as new engineered board				
		BQ 8 / Page 21; omit	Item H deleted (insert 0 for quantity)			
		Query regarding spec F21 and source of existing	Of the 86 copings item B allows for 77 to be removed and set aside for			
3	28/05/2019	stones	re-use			
		removed and set aside for reuse on BQ 2 / Page 4	Itama C. Nova for their reinstatement require these items. "from	GYA	28-May-19	
			Items G - N are for their reinstatement re-using those items. "from store" refers to storage by contractor in this instance.			
			There is allowance for 9 copings to be disposed of (item C) and			
			replaced with new on page 5 items A & B			
			replaced with new on page 5 items // & 5			
			Please note measurement preamble in Appendix D Item F page 3			
			, , , , , , , , , , , , , , , , , , ,			

## TAVISTOCK GUILDHALL GATEWAY PROJECT

# QUESTIONS & RESPONSES DURING TENDER PERIOD

Date added	Question	Response	Responder	Date of Response	Date of posting
30/05/2019	Query related to automated opening of GD02 as defined in BQ 2/35/D	GD02 and GD07 require automated opening. Refer to NBS L10 550 and 555. Drawings C390 (GD02) and A459 (GD07) note the need for automated openings.	GYA	30-May-19	
		GD 07 is BQ 10/27B	THA		
31/05/2019	Query on cupboard doors in F36 & F37	In F36 the cupboard door - 2 has been omitted from drawing C382		03-Jun-19	
		In F37 an opening has been infilled to F40 and a new riser door added on C382	ТНА		
		BQ 6a re-issued with:			
		Page 3 item D1 added for the infilling in F37			
		BQ 6b re-issued with:			
		Page 3 items C, D, G,& K modified to omit F36 cupboard - 2			
		Page 4 item A1 added and items B, C, D & E modified for new riser door			
04/06/2019	Contractor unable to make contact with specialist copper company Rukki	Company has recently retreated from UK operations.			
	BQ 8/12 E - G	GYA have contacted the copper supplier Aurubis (Graeme Bell) and they have advised that Metal Solutions can fabricate / supply the panels in the UK.	GYA	07-Jun-19	
		http://www.metalsolutions.uk.com/aurubis-nordic-copper-roofing- and-cladding.htm Contact Phil Downey - phil@metalsolutions.uk.com - 01204 491800			
	30/05/2019	30/05/2019  Query related to automated opening of GD02 as defined in BQ 2/35/D  31/05/2019  Query on cupboard doors in F36 & F37  O4/06/2019  Contractor unable to make contact with specialist copper company Rukki	30/05/2019  Query related to automated opening of GD02 as defined in BQ 2/35/D  GD02 and GD07 require automated opening. Refer to NBS L10 550 and 555. Drawings C390 (GD02) and A459 (GD07) note the need for automated openings.  GD 07 is BQ 10/27B  In F36 the cupboard door - 2 has been omitted from drawing C382  In F37 an opening has been infilled to F40 and a new riser door added on C382  BQ 6a re-issued with:  Page 3 item D1 added for the infilling in F37  BQ 6b re-issued with:  Page 3 item SC, D, G,& K modified to omit F36 cupboard - 2  Page 4 item A1 added and items B, C, D & E modified for new riser door  Contractor unable to make contact with specialist copper company Rukki  BQ 8/12 E - G  GYA have contacted the copper supplier Aurubis (Graeme Bell) and they have advised that Metal Solutions can fabricate / supply the panels in the UK. http://www.metalsolutions.uk.com/aurubis-nordic-copper-roofing-and-cladding.htm	30/05/2019  Query related to automated opening of GD02 as defined in BQ 2/35/D  GD02 and GD07 require automated opening. Refer to NBS L10 550 and 555. Drawings C390 (GD02) and A459 (GD07) note the need for automated openings.  GD 07 is BQ 10/27B  THA  THA  31/05/2019  Query on cupboard doors in F36 & F37  In F36 the cupboard door - 2 has been omitted from drawing C382  BQ Ga re-issued with:  Page 3 item D1 added for the infilling in F37  BQ Gb re-issued with:  Page 3 item D1 added for the infilling in F36 cupboard - 2  Page 4 item A1 added and items B, C, D & E modified for new riser door  Company Rukki  BQ 8/12 E - G  GYA have contacted the copper supplier Aurubis (Graeme Bell) and they have advised that Metal Solutions can fabricate / supply the panels in the UK.  http://www.metalsolutions.uk.com/aurubis-nordic-copper-roofing-and-cladding.htm	30/05/2019  Query related to automated opening of GD02 as defined in BQ 2/35/D  GD02 and GD07 require automated opening. Refer to NBS L10 550 and 555. Drawings C390 (GD02) and A459 (GD07) note the need for automated openings.  GD 07 is BQ 10/27B  THA  31/05/2019  Query on cupboard doors in F36 & F37  In F36 the cupboard door - 2 has been omitted from drawing C382  In F37 an opening has been infilled to F40 and a new riser door added on C382  BQ 6a re-issued with:  Page 3 item D1 added for the infilling in F37  BQ 6b re-issued with:  Page 3 item D1 added for the infilling in F37  BQ 6b re-issued with:  Page 3 item SC, D, G, & K modified to omit F36 cupboard - 2  Page 4 item A1 added and items B, C, D & E modified for new riser door  O4/06/2019  Contractor unable to make contact with specialist copper company Rukki  BQ 8/12 E - G  GYA have contacted the copper supplier Aurubis (Graeme Bell) and they have advised that Metal Solutions can fabricate / supply the panels in the UK.  http://www.metalsolutions.uk.com/aurubis-nordic-copper-roofing-and-cladding.htm

## TAVISTOCK GUILDHALL GATEWAY PROJECT

## QUESTIONS & RESPONSES DURING TENDER PERIOD

Question number	Date added	Question	Response	Responder	Date of Response	Date of posting
Issue 3						
7	11/06/2019		The NBS spec is correct. Change all BQ item descriptionss with K10/680 to delete "Thistle Magnetic Plaster" and use " Thistle Multi Finish Plaster"	ТНА	12-Jun-19	
8		Drawings GA 220-224	Cleaning 2/27/B amend quantity to 482m2  Light brushing 2/27/M; allow for all stonework to receive an initial light brush to remove loose face in order for inpsection by Architect to determine any further action. Approx area 830m2	ТНА	12-Jun-19 12-Jun-19	
9	12/06/2019	Drawing C392 Typical Flood Board Details	Uploaded onto web site	GYA	12-Jun-19	