

window types and treatments

- L10/210** Timber sash windows - Undertake timber repairs, overhaul and redecoration
- L10/220** Fixed timber windows - Undertake timber repairs, overhaul and redecoration
- L10/310** Crittall steel window in timber subframe. Undertake repairs, overhaul and redecoration
- L10/210** Timber sash windows - Requiring significant structural repairs, overhaul and redecoration.

Existing window requiring metal bars to be removed and existing surrounds to be made good.



tavistock guildhall **guildhall square west elevation as proposed**

<p>general</p> <ul style="list-style-type: none"> • all drawings are copyright • do not scale drawing • report all discrepancies to project administrator • all dimensions to be checked on site 	<p>key</p>	<p>notes</p> <p style="color: red; font-weight: bold; font-size: 12px;">Stage 4 - Tender</p> <p>Note: Alterations and upgrades to existing fabric detailed on demolition plans, details and specification</p>	<p>rev</p> <p>T1: 08.02.19 - NBS Specification References Amended</p>	<p>project: Tavistock Guildhall and Police Station</p> <p>date: Oct 2018</p> <p>scale: 1:50 @ A1 1:100 @ A3</p> <p>drawing title: Window Repair - Guildhall Sq. Elev.</p> <p>job no: 1041</p> <p>drawing no: GA-230</p> <p>drawn: if</p> <p>rev: T1</p> <p style="font-weight: bold; font-size: 12px;">gillespie yunnie architects</p>
---	-------------------	---	--	--